


[www.mjbi.com](http://www.mjbi.com)

# Frame 9001E Rotor Repair System



## Frame 9 rotor overhaul

- Pre-strip-down balance and inspection
- Rotor disassembly
- NDT facilities
- Individual blade and wheel coating
- Latest coating technologies
- Individual wheel balancing
- Rotor re-blade
- Rotor stacking system
- Rotor reassembly
- Rotor balance and run-outs
- Rotor storage containers
- Comprehensive customer report

MJB's extensive Frame 9 GTG capabilities and stock Frame 9E Rotor enables rapid response to scheduled and emergency shutdown requirements.

MJB's customized air-conditioned state-of-the-art repair facility extends to 8000 sq. m, with full capabilities to repair heavy industrial gas turbine stationary and rotating parts including FA & DLN Technology.

MJB can now offer re-blade and balancing of rotors up-to and including Frame 9 and provide clients with a "stock advantage" by having a full set of parts for all Frame sizes including spare rotors to enable us to continue to ensure customers in the region and internationally have access to critical parts on an urgent basis.

MJB has invested in a complete FS9001E Thermal Block which enables MJB to offer, the associated capitals fully refurbished and warranted at a significantly reduced price compared to new and the ability to supply replacement casings to clients with an emergency requirement.

